



FIG. 3



F1G. 4



F1G. 5




FIG. 6




FIG. 8(A)


(A) RINGING SIGNAL SENDING APPARATUS 10


	RELAY SWITCHES SW1 AND SW2	RELAY SWITCHES SW3 AND SW4
RINGING	0 2	ON
LOW-IMPEDANCE FEED	OFF	DON'T CARE
HIGH-IMPEDANCE FEED	ON	OFF


FIG. 8(B)

(B) RINGING SIGNAL SENDING APPARATUS 10a

	RELAY SWITCHES SW1 AND SW2	RELAY SWITCHES SW3 AND SW4
RINGING	0 N	DON'T CARE
LOW-IMPEDANCE FEED	OFF	ON
HIGH-IMPEDANCE FEED	OFF	OFF










FIG. 12





FIG. 13



F1G. 14






FIG. 15


ż




F1G. 16



F1G. 17



F16. 18



F1G. 19




FIG. 20 PRIOR ART




FIG. 21 PRIOR ART